

Office of the Executive Engineer Provincial Division, P.W.D Nainital



E_Mail:- cepdpwdntl@gmail.com

Latter No. 875 127 ma.

Date - 2/5/2021

Certificate

This is to certified that the school building of Longview Public School, Tallital, Nainital are found well maintained and running in good condition till date. It has been observed in visual inspection of Assistant Engineer and Additional Assistant Engineer that the existing buildings seems to be safe at present under normal circumstances, as per structural Engineer's report.

Place :- Nainital

Date: - 02-05-2022

(Er. M.M.S. Pundir) Executive Engineer

Provincial Division,

Executive Engineer Provincial Division, P.W.D., Namital